

This report shows the number of safety defects (split by defect type and location) completed by Somerset Highways within your division for the previous month.

For reference, codes starting with T or U represent Unclassified roads.

Mendip South ED

• CW- Carriageway Pothole	A361/670	STOCKBRIDGE LANE TO STEANBOW - WEST PENNARD	21
• CW- Edge Loss	T2102/20	MILL STREET - BALTONSBOROUGH	7
• CW- Carriageway Pothole	T2123/50	WOODLANDS ROAD - WEST PENNARD	5
• CW- Carriageway Pothole	T2267/50	WYKE FARM TO SNAGG FARM - LAMYATT	5
• Multiple CW Safety Defects	T2151/20	PENNARD LANE - WEST PENNARD	4
• CW- Carriageway Pothole	T2102/20	MILL STREET - BALTONSBOROUGH	3
• Multiple CW Safety Defects	U2145/10	LOOKS LANE - BUTLEIGH WOOTTON	3
• CW- Edge Loss	U2147/10	KENNARD MOOR DROVE - COXBRIDGE	3
• CW- Carriageway Pothole	A361/650	WOODLANDS ROAD TO STOCKBRIDGE LANE - WEST PENNARI	2
• CW- Carriageway Pothole	A361/720	WHITSTONE HILL - PILTON	2
• Multiple CW Safety Defects	B3136/110	LAMBERTS HILL - PILTON	2
• CW- Carriageway Pothole	T2102/30	MOORHOUSE - BUTLEIGH	2
• GY- Difference in Level	T2267/50	WYKE FARM TO SNAGG FARM - LAMYATT	2
• CW- Edge Loss	T2267/50	WYKE FARM TO SNAGG FARM - LAMYATT	2
• CW- Carriageway Pothole	U2145/10	LOOKS LANE - BUTLEIGH WOOTTON	2
• CW- Carriageway Pothole	A361/660	WOODLANDS ROAD TO STOCKBRIDGE LANE - WEST PENNARI	1
• CW- Carriageway Pothole	A361/690	STEANBOW / PARK HILL - PILTON	1
• CW- Edge Loss	A361/690	STEANBOW / PARK HILL - PILTON	1
• GY- Blocked Drainage System	A361/720	WHITSTONE HILL - PILTON	1
• MH- Dislodged Cover	A361/720	WHITSTONE HILL - PILTON	1
• CW- Carriageway Pothole	A361/730	EAST COMPTON ROAD - PILTON	1
• CW- Carriageway Pothole	A37/680	FOSSE WAY - PYLLE	1
• CW- Carriageway Pothole	A37/730	FOSSE WAY - PYLLE	1
• CW- Edge Loss	A371/230	SNAGG LANE TO REDLANDS FARM LANE - DITCHEAT	1
• CW- Carriageway Pothole	A371/230	SNAGG LANE TO REDLANDS FARM LANE - DITCHEAT	1
• TR - Tree Down on Highway	A371/240	REDLANDS FARM LANE TO PRESTLEIGH ROAD - EVERCREECH	1
• CW- Carriageway Pothole	A371/260	REDLANDS FARM LANE TO PRESTLEIGH ROAD - EVERCREECH	1
• CW- Carriageway Pothole	B3081/550	BRUTON ROAD - EVERCREECH	1
• CW- Carriageway Pothole	B3081/560	BRUTON ROAD/HIGH STREET/PRESTLEIGH ROAD - EVERCREECH	1
• CW- Edge Loss	B3136/110	LAMBERTS HILL - PILTON	1
• CW- Carriageway Pothole	B3136/110	LAMBERTS HILL - PILTON	1
• CW- Flooding in Carriageway	B3136/110	LAMBERTS HILL - PILTON	1
• CW- Carriageway Pothole	T1368/40	SUB ROAD - BUTLEIGH	1
• CW- Carriageway Pothole	T1368/50	SUB ROAD - BUTLEIGH WOOTTON	1
• CW- Carriageway Pothole	T2101/70	BARTON ROAD - BUTLEIGH	1
• CW- Carriageway Pothole	T2102/50	WATCHWELL DROVE - BUTLEIGH	1
• CW- Carriageway Pothole	T2105/30	REYNOLDS WAY - BUTLEIGH	1
• CW- Carriageway Pothole	T2105/40	REYNOLDS WAY - BUTLEIGH	1

This report shows the number of safety defects (split by defect type and location) completed by Somerset Highways within your division for the previous month.

For reference, codes starting with T or U represent Unclassified roads.

Mendip South ED

• CW- Carriageway Pothole	T2123/40	COXBRIDGE DROVE - COXBRIDGE	1
• CW- Edge Loss	T2123/40	COXBRIDGE DROVE - COXBRIDGE	1
• CW- Edge Loss	T2123/50	WOODLANDS ROAD - WEST PENNARD	1
• CW- Step in Level	T2151/20	PENNARD LANE - WEST PENNARD	1
• CW- Carriageway Pothole	T2185/40	COURT BARN LANE - WEST BRADLEY	1
• TR - Tree Down on Highway	T2236/10	FOLLY COTTAGES TO ARTHURS BRIDGE - DITCHEAT	1
• Multiple CW Safety Defects	T2236/20	WRAXALL ROAD TO FOLLY COTTAGES - DITCHEAT	1
• GY- Broken Grate\ Frame	T2239/10	LEIGHTON LANE - EVERCREECH	1
• CW- Edge Loss	T2296/25	WESTCOMBE HILL - BATCOMBE	1
• CW- Carriageway Pothole	T2387/10	HIGHER WESTHOLME ROAD - PILTON	1
• CW- Carriageway Pothole	T5760/20	PERRY HILL - LYDFORD ON FOSSE	1
• CW- Debris in Carriageway	U2140/10	CEDAR WALK - BUTLEIGH	1
• GY- Collapsed Chamber	U2140/10	CEDAR WALK - BUTLEIGH	1
• CW- Carriageway Pothole	U2147/10	KENNARD MOOR DROVE - COXBRIDGE	1
• CW- Edge Loss	U2189/10	TILHAM LANE - BALTONSBOROUGH	1

Total: **104**